

### Corner Storage Valdosta Outdoor Storage Screening Plan

Outdoor Storage to be screened by an 8' chain link fence with 90% visibility screening mesh. Due to the proximity of the drive aisles to the property line, we will have to determine if we can also squeeze in the required landscape buffer. Facing Bemiss Rd. we will work with the County Arborist to utilize existing canopy trees and determine any additional screening necessary to meet planning requirements. Customers will enter outdoor storage through side driveway behind second retail building.



Existing Canopy Trees on Left side of Property. Fencing to go behind these trees.

Attachment: CU-2022-02 agenda item packet - City Council (3351 : Conditional Use Permit CU-2022-02)