

LMIG Resurfacing Completed – 6.56 miles

- Briarwood Road – .25 Miles
- Dasher Grove Road – .56 Miles
- Howell Drive - 0.32 Miles
- River Road – 1.37 Miles
- Westside Road - 0.76 Miles
- Old US 41 – 0.50 Miles
- Eastridge Drive – 0.21 Miles
- Laurelwood North – 0.05 Miles
- Laurelwood South – 0.13 Miles
- Meadowood Circle – 0.07 Miles
- Springbrook Drive – 0.28 Miles
- Summer Field Drive – 0.29 Miles
- Fiddlers Bend Drive – .07 Miles
- Pebble Creek Drive – .79 Miles
- Sandy Run Drive – 0.28 Miles

Maintained GDOT PACES Ratings, Inspections of Subdivision Construction, Road Inventory and Traffic Signals

Plan & Plat Review

Plan Review – 51

- Commercial – 34
- Erosion and Sediment Control – 15
- Subdivision – 2

Plat Review – 134

- Combination – 47
- Exempt – 28
- Family – 8
- Final – 8
- Minor – 26
- Preliminary – 9
- Revision – 8

CO Inspections - 25